



Equipment Inspection Report

Inspection Date: [Click here to enter text.](#)

Category Code: [Click here to enter text.](#)

General Information

Make: JACOBSEN	Model: GREENSKING IV
Serial Number: 6230605104	Year: 2017
<input checked="" type="checkbox"/> 2WD <input type="checkbox"/> 3WD <input type="checkbox"/> 4WD	Hours (if applicable): 206

Accessories Included: [Click here to enter text.](#)

General Appearance

Front Body Panels	<input type="checkbox"/> Excellent condition (no scratches) <input checked="" type="checkbox"/> Good condition (minor scratches) <input type="checkbox"/> Average condition (some scratches) <input type="checkbox"/> Poor condition	Rear Body Panels	<input type="checkbox"/> Excellent condition (no scratches) <input checked="" type="checkbox"/> Good condition (minor scratches) <input type="checkbox"/> Average condition (some scratches) <input type="checkbox"/> Poor condition
Seat/Frame	<input type="checkbox"/> Excellent condition <input checked="" type="checkbox"/> Good condition (normal wear) <input type="checkbox"/> Average condition (minor tear) <input type="checkbox"/> Poor condition	Wheels/Tires/Tracks	<input type="checkbox"/> Excellent condition <input checked="" type="checkbox"/> Good condition (normal wear) <input type="checkbox"/> Average condition (worn) <input type="checkbox"/> Poor condition (no tread)
Canopy/Cab	<input type="checkbox"/> Excellent condition <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Average condition <input type="checkbox"/> Poor condition	Rollers/Reels/Decks Attachments	<input type="checkbox"/> Excellent condition <input type="checkbox"/> Good condition <input checked="" type="checkbox"/> Average condition <input type="checkbox"/> Poor condition (rusty)

Operator Station

Gauges	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing	Machine Controls	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing
Machine Frame	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing	Brakes	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing
Reels/Head	<input type="checkbox"/> 5 Blade <input type="checkbox"/> 10 Blade <input type="checkbox"/> 7 Blade <input type="checkbox"/> 11 Blade <input type="checkbox"/> 8 Blade <input checked="" type="checkbox"/> 15 Blade <input type="checkbox"/> 9 Blade	Tines	<input type="checkbox"/> Excellent condition <input type="checkbox"/> Average condition <input type="checkbox"/> Needs sharpening <input type="checkbox"/> Missing

Power Train

Engine Type	<input checked="" type="checkbox"/> Gasoline <input type="checkbox"/> Diesel <input type="checkbox"/> Electric MFG: Click here to enter text. HP: Click here to enter text.	Engine Condition	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Runs, needs minor repairs <input type="checkbox"/> Does not run <input type="checkbox"/> Bad battery
PTO/Transmission	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Slips in drive <input type="checkbox"/> Reverse out <input type="checkbox"/> Does not move	Drive Belts	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing
Electric Motors	<input type="checkbox"/> Normal working condition <input type="checkbox"/> Leaking <input type="checkbox"/> Not working <input type="checkbox"/> Missing	Hydraulics	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Pump Leaks <input type="checkbox"/> Hoses broken or leaks <input type="checkbox"/> Valve bank leaks

Additional Comments: SLIGHT RUST ON ROLLERS

Inspected by: _____